



TECHNICAL TIP - CHECKING AN AMPLIFIER

(KAE 234 or 248)

Red Probe	Black Probe	Resistance Value
2	7	10.1
3	1	2215 or 2.215k
3	6	16.7
6	1	2199 or 2.199k
6	3	16.7
7	2	10.1

Amp Probe AC/DC 620T Multi-meter with 0.01 probe to probe resistance.